FUSS & O'NEILL
Manufacturing Solutions, LLC
"Enhancing Productivity"

X	Basic Skill
X	CounterMeasure
X	Accessibility
X	Safety
X	Mistake Proofing
X	Productivity

Simple Tool Guides Eliminate Hand Alignment

SIMONDS INTERNATIONAL

1) Having an operator align a work piece by hand consumes resource unnecessarily.

2) In this example, operators were required to hand align parts each time before punching slots. This caused added time for proper positioning, induced variability, and even created scrap.

3) Simple guide functions were added. The operator can now produce with quick, repeatable, and accurate results. Operators should never be subject to an unstable process.

John Kravontka | 146 Hartford Road – Manchester, CT 06040 | (800) 286-2469 x5399 | JKravontka@FandO.com